



Inspection Date Report No Client June 27, 2018 611310988

Property Address

1125 Maxwell Ln, #X Hoboken, NJ 07030

Inspector

Daniel Lin (License# 24GI00119200)

This report lists the systems and components inspected by this company. Items not found in this report are considered beyond the scope of this inspection, and should not be considered inspected at this time.

"APPEAR SERVICEABLE" means that we did not observe conditions that would leave us to believe major problems existed with this system or component. The item is cable of being used. Some serviceable items may, however, show wear and tear. Other conditions if applicable, will be noted in the body of the report.

Significantly deficient systems or components will be identified as "Non functional / unsafe / worn / near end of lifespan." When in the inspector's opinion, an item is "significantly deficient", the reason will be within the body of the report.

Please read the entire report for all items.

Present during the Inspection

Notice: This report contains technical information that may not be readily understandable to the lay person. Therefore a verbal consultation with the inspector is a mandatory part of this inspection report. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of this report's contents. If you were not present during this inspection please call the office to arrange for your verbal consultation.

	coent during the mopeotion
Χ	Client
Χ	Buyer's Agent
	Seller's Agent
	Seller
	Occupant
Ins	spector
	Daniel Lin (License# 24GI00119200)
In	spection Date
	June 27, 2018
St	art Time
	6:15 PM
Co	ompletion Time
	7:45 PM
Th	ne weather condition at the time of the inspection was Dry
Αŗ	proximate temperature during inspection 70° F
Pr	operty Information
	1125 Maxwell Ln, #X, Hoboken, NJ 07030
Th	e subject property inspected
	Condominium
Αŗ	proximate year building was built
	2008
St	ated by
	Listing

Notice: It is always wise to check with the building department for permit information, especially if additions or alterations are noted.

IMPORTANT NOTICE TO THIRD PARTIES OR OTHER PURCHASERS: RECEIPT OF THIS REPORT BY ANY PURCHASERS OF THIS PROPERTY OTHER THAN THE PARTIES) IDENTIFIED ON THE CONTRACT IS NOT AUTHORIZED BY THE INSPECTOR. THE INSPECTOR STRONGLY ADVISES AGAINST ANY RELIANCE ON THIS REPORT. WE RECOMMEND THAT YOU RETAIN A QUALIFIED PROFESSIONAL INSPECTOR TO PROVIDE YOU WITH YOUR OWN INSPECTION AND REPORT ON THIS PROPERTY.

Summary

This section is provided as a courtesy for quick access to the information within the inspection report.

It is not intended as a substitute for reading the inspection report.

Subject unit is located within a condominium complex - accessible portions / interior of the property was inspected and reported upon.

Plumbing

Hot water heating system is owned / maintained by condominium association & outside the scope of inspection, was operating at time of inspection.

Electrical

Outlet not operational at balcony. Unable to reset GFCI device at balcony. Repair is needed. Light not operational at main bathroom - repair is needed.

Interior & Features

Door rubs frame at bedroom 1 bathroom, loose hinge / missing pin noted. Door does not latch at bedroom 2. Lock handle missing at various locations (e.g. main bathroom, bedroom 1 bathroom, bedroom 1, bedroom 2) doors. Adjustment / repair is needed.

Broken sash balance (window does not stay open) noted at bedroom 1 - repair is needed.

Ceiling cracks noted.

Wear / aging noted at flooring. Lifted flooring noted by main bathroom. Cracked floor tiles noted at main bathroom.

Loose exterior trim noted at balcony - repair is needed.

Smoke detectors / fire exit / sprinklers were not inspected. Have the Township check and approve the system (part of State Certificate of Occupancy requirements).

Regular cleaning of dryer exhaust duct is needed for fire safety.

Bathroom

Wear noted at bedroom 1 bathroom sink cabinet. Gap noted at master bathroom countertop to wall connection - recommend sealing to prevent further moisture penetration / damage.

Damaged weather stripping noted at main & master bathroom shower doors - repair is needed.

Wood Destroying Insects

Inspection to the wood destroying insect was limited due to lack of access to entire building, cluttered storage, and interior finishings. The inspector can not guarantee that wood destroying insect does not exist. Further investigation may be needed to ensure the house is free of insect damage/infestation.

NOTES

Every effort has been made to perform a detailed and thorough inspection. However, due to interior finishings & furnishings / storage, visibility is limited. Evaluation is conditional to the time of inspection, things may change between the time of inspection and closing. This office recommends a final walkthrough before closing to check areas that were not visible during the time of inspection. Inquire with this office regarding fee & scheduling for the final walkthrough.

Plumbing

Main Water Supply					
Description					
Shutoff Valve Loca	ti Basement	Garage	Closet	Lower bathroom	X Unknown
Material	Copper	Galvanized	Plastic	Lead	X Unknown
Approx Size	3/4"	1"	1.5"	X Unknown	Not Inspected
Observation				_	
X Serviceable	Worn	Near and of lifeana	n Unsafe	Not Functional	X Not fully visible
Main Valve Operation	→	Near end of lifespar X Not Tested	Handle	Missing	Leaking
Pressure	Service off	X Serviceable	Irregular	High Pressure	Low
Damage	Copper and Concre		Softener	Softener Installed	Softener Leaks
Asbestos	Extension cord	Missing filter	Solienei	Soliteriei ilistalleu	Soliterier Leaks
Association	Extension cord	Iviiosing litter			
Comment					
Notice: Well pumps are beyon	d the scope of this inspection.				
Water Supply Lines					
Description					
, Material	X Copper	Galvanized	Pex	Lead	X Unknown
Observation					
X Serviceable	Worn	Near end of lifespar	n Unsafe	Not Functional	X Not fully visible
	Shutoff Corrosion	Minor Corrosion	Moderate Corrosio		Active Leaks
Damage Pressure Loss	Minor	Moderate	Poor	Loss	Unable to test
Noise	Lack Support	Crossed with Sanita		Not Insulated	Mixed
Asbestos	Condensation	O100000 With Odnik	arr nor repair	INOT INIOCIATOR	WIIAGG
	Condensation				
Comment					
	oipes inside walls cannot be judg oing systems have experienced o		Water quality testing or testing t	ior hazards such as lead is not pa	art of this inspection. Be advised tha
Waste Lines					
Description					
Copper	Galvanized	PVC	Lead	Cast Iron	X Unknown
Observation				_	_
X Serviceable	Worn	Near end of lifespar	n Unsafe	Not Functional	X Not fully visible
Damage	Minor Corrosion	Moderate Corrosion		Active Leaks	Moisture Stains
Lack Support	Insufficient Fall	Open Line	Trap improper	Active Leaks	Indistare otams
Vents	X Serviceable	None Observed	Improper	Missing	X Not fully visible
Asbestos	7. 00. 1100000.0				rection, themse
_					
Comment					

Notice: City sewer service, septic systems and all underground pipes are not a part of this inspection. Future drainage performance is also not determined. Be advised that some "ABS" plastic piping systems have experienced documented problems. Contact the manufacturer or plumbing expert for further information and evaluation. All of vent/trap pipes were not visible.

Plumbing

Fuel System							
Description							
Shut Off Valve Loc	Exterior	Basement	Garage	Kitchen	X Unknown		
Туре	X Natural Gas Meter	Oil Tank	LPG Tank	Propane Gas	Fuel Oil		
Observation					V N A C II A T II		
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible		
Damaged	Proofed	Not Proofed	Ground/Concrete	Corroded			
Strained	Lack Support	Improper Pipe	Improper Use	Exposed	Oil Lines		
Low	Unions / Bushings	Copper					
Comment							
Notice: Underground piping & f	uel tanks cannot be judged. Pipe	es inside walls or pipes concealed f	rom view cannot be judged and th	ne inspector does not perform te	ests for gas leaks or pipe size.		
		age tanks is not part of this inspect					
Water Heater							
Description							
Description	Decement	Carago		Closet	X Unknown		
Location Fuel	Basement Gas	Garage Electric	Kitchen Oil	Closet	Tankless (see Heating)		
		<u> </u>	─	Tankless	Unknown		
Capacity	29 gal	50 gal	80 gal	Talikiess	Ulikilowii		
Observation							
Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible		
Damaged	Pilot Light	Leaking	Corrosion	Flame	Scorching		
Shut Off Valve	Installed	Missing / Broken	Leaking	Corrosion	Missing Red Label		
TPR	Installed	Not Installed	Missing Pipe	Improper	Too short		
Leaking	Missing	Threaded	Capped	Unsafe	Corrosion		
Combustion Air	Supply Air OK	Blocked	Poor				
Vent Flue	Piping OK	Missing	Loose	Foil tape	Improper		
	Back Draft	Improper Angle	Elbows	Clearance	Soot		
Seismic Straps	Serviceable	Not Installed	Improper		_		
Thermal Blanket	Serviceable	Not Applicable	Damaged / Missing				
No Catch Pan	Protect	Enclosure Door	Firewall	Garage Floor >18"	No Drain Line		
	_		_				
0							
Comment			tian 0 a.utaiala tha aaana	-f !t!	sting at time a of in an action		
not water neating syste	em is owned / maintained	I by condominium associa	tion & outside the scope	or inspection, was opera	ating at time of inspection.		

Notice: Estimate of remaining life is not part of this inspection. Solar systems are not part of this inspection. Hot water recalculating pumps/systems are not part of this inspection. Unable to fully inspect vent pipe.

Heating

Heating Description					
Location Heating Type Fuel Type Approx BTU Manufacturer Model Serial Manufacturing Date	X Living Room X Heat Pump X Electric X Unknown X Trane X GETB00913A X W07B15653 X 2007	X Living Room X Heat Pump X Electric X Unknown X Trane X GETB01813A X W07C16194 X 2007	X Living Room X Heat Pump X Electric X Unknown X Trane X GETB01513A X W07C16189 X 2007	2007	
Comment					
commonly used in heating systen			ualified heating contractor for safe by laboratory testing and is beyon		. Asbestos materials have been
Heating Observation	10/	No an and of life and		Not Foundant	V No. 6 db . 2 db la
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
X Operational	Damaged	Not Serviced Pilot not lit	Unresponsive	Not Tested Utilities off	No Service
Not Applicable Complete Evaluation	Not Inspected Clean / Service	Unusual Noise	Ignition malfunction Asbestos	Upgrades	Corrosion
Burner	Burner Serviceable	Unusual flame	Not visible (closed sy		Rust / Scorch / Soot
Thermostat	Broken	Poor Location	Repairs	Low battery	Loose
Air Filter	Improperly sized	Dirty	Hold-down	Gap	Insufficient Clearance
Furnace	Low Temperature	Air Leaks	Cut Doors	Moisture	Termination Location
Boiler	High Pressure	Low Temperature	Low Pressure	Boiler Leaks	Fuel tank leak
	Leaks	Corrosion	TPR	Fittings	Expansion Tank
No Shutoff Label	Not Red	Moisture	Not Tested (AC)	Door switch broken	
Comment	<u></u>				

Electronic air cleaners, humidifiers and dehumidifiers are beyond the scope of this inspection - have these systems evaluated by a qualified individual. The inspector is not equipped to thoroughly inspect heat exchangers for evidence of cracks or holes, as this can only be done by dismantling the unit or other technical procedures. Some furnaces are designed in such a way that inspection is almost impossible. Thermostats are not checked for calibration or timed functions. Safety devices are not tested by this company.

Heating

Distribution

Description					
X Ducts & Regi	sters Pipes & Convectors	Pipes & Radiators	Pipes, Radiators &	C Air Handler	Electric Baseboard
X Serviceable	Damaged	X Not Fully Visible	Corroded ducts	Corroded pipes	Worn
Observation					
	Disconnected	Registers	Asbestos	Crushed Ducts	Leaks
Uneven volun		Zone Valve	Circulating Pump	Heat Source	
Room Radiate	· '	Corrosion	Fittings	Damaged	
Recommenda	· ·	Asbestos	Safety Upgrade	Cleaning	
Humidifier	Moisture	Not connected	Not operational		
Comment					
Notice: Adequacy, efficient	ciency or even heat distribution of the sys	tem through the house is not part	of this inspection. Asbestos mat	erials have been commonly use	ed in heating systems. Determining
the presence of asbes	tos can ONLY be performed by laboratory	testing and is beyond the scope	of this inspection. Electronic ai	r cleaners, humidifiers and dehi	umidifiers are beyond the scope of
Venting					
•					
Observation					
Serviceable	Damaged	Not fully visible	Inaccessible	Unsafe	
Back Venting	Soot / Rust	Combustible clearar	nd Improper rise	Improper elbow ar	ngle Wrong Materials
Observation	_				
Terminates n	ear wind Barometric Damper		Undersized	Moisture	
Repairs	Asbestos	Safety Upgrade			
Repairs	Asbestos	Safety Upgrade			
Repairs	Asbestos	Safety Upgrade			
Repairs Comment	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
	Asbestos	Safety Upgrade			
Comment			page of ashestes can ONLY be a	orformed by Jahoratory testing	and is bound the scope of this
Comment	Asbestos erials have been commonly used in heating		ence of asbestos can ONLY be p	erformed by laboratory testing a	and is beyond the scope of this
Comment Notice: Asbestos mate			ence of asbestos can ONLY be p	erformed by laboratory testing a	and is beyond the scope of this
Comment Notice: Asbestos mate			ence of asbestos can ONLY be p	erformed by laboratory testing a	and is beyond the scope of this
Comment Notice: Asbestos mateinspection. Combustion Air			ence of asbestos can ONLY be p	erformed by laboratory testing a	and is beyond the scope of this
Comment Notice: Asbestos mateinspection. Combustion Air Observation	erials have been commonly used in heatin	ng systems. Determining the prese			
Comment Notice: Asbestos mateinspection. Combustion Air	erials have been commonly used in heatin		ence of asbestos can ONLY be p None Provided Recommend sealin	Not visible	and is beyond the scope of this
Notice: Asbestos mateinspection. Combustion Air Observation Serviceable	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos mateinspection. Combustion Air Observation Serviceable	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos mateinspection. Combustion Air Observation Serviceable	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	
Notice: Asbestos matrinspection. Combustion Air Observation Serviceable Blocked	erials have been commonly used in heatin	ng systems. Determining the prese	None Provided	Not visible	

Air Conditioning

Description									
Not Applicable Type Power	Location Central Air Package Unit 120 Volt	X	Living Room Heat Pump - Air Wall Unit 240 Volt	X	Living Room Water Source Window Unit Unknown	X	Living Room PTAC Geothermal	Unknown Split System	
X Serviceable	Worn		Near end of lifespan		Unsafe	F	Not Functional	X Not fully visible	
X Operational	Not Tested		Not Inspected	L	Not fully evaluated	L	No Service	Did not respon	nd
Comment									
Observation									
X Serviceable	Worn		Near end of lifespan		Unsafe	Г	Not Functional	X Not fully visible	е
Inspection Issues	No Power	Г	Below 65	Г	Natural Gas	Г	Warm Air Only	Unusual Noise	
Electrical Disconnect	Present		Not Present		Improper		Exposed Conduit	Not Grounded	l
Condense Lines	Properly Installed	Χ	Not Fully Visible		Termination Point		Disconnected	Moisture	
	Leaking		No Trap		Too Short		Pinched		
Refrigerant Lines	Present		Damaged	Х	Not Fully Visible		Exposed	Missing	
Not Level	Pads		Rusted		Float Valve / Pump		Leaking	Too Low	
Temperature Differer	System Coil		Circulation		Junction Box Loose		Junction Box Cover	Pump Auxiliar	У
Ice	Recommend Servicin	L	Moisture	L	Repair needed	L	No catch pan		
Comment									

Notice: The inspector does not perform pressure tests on coolant systems: therefore no representation is made regarding coolant damage or line integrity. Subjective judgment of system capacity is not part of the inspection.

Electrical

Electric Panel

Description					
Main Panel Location	Entranceway	Basement	X Interior	Exterior	Unknown
Sub Panel Location	Basement	Garage	Interior	Attic	Unknown
Rating	60A	100A	125A	200A	X Unknown
Service Wire	Aluminum Service	Copper Service	Branch Wire	X Unknown	X Copper Branch
Wiring Methods	Metal Conduit	Non-Metallic Cable	Knob & Tube	Plastic Conduit	X Unknown
Panel Type	X Breaker	Fuse	Voltage	X 120V	X 220V
Observation					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	No service
Main Locked	Sub Locked	Power Off	Blocked	X Painted	Not Opened
Main Ground	X Present	Loose	Water Line	Ground Rod	Not Visible
No Main	6 Breakers		_	_	
Main Panel	X Serviceable	Improper Wiring	Multi tap	Over Fused	Bushing / Clamps
Labels Missing	Breaker Off	Scorched	Melted	Rust	Not Bonded
Unprotected	Fused Wires	Loose		_	_
Sub Panel	Over Fused	Bushings / Clamps	No Labels	Scorched	Melted
Rust	Same Buss	Not Bonded			
Outdated	Tap Wires	No Antioxidant	Couplers	Dead front cover m	nis:
Moisture	Mixed Breaker	Loose Breaker	Inoperable Breaker	Upgraded	
Comment					

Notice: Six or fewer breakers usually do not require a main breaker, however this may indicate minimal electrical capacity. If the service amperage is less than 100, upgrade may be needed to operate larger electrical appliances.

Electrical

Description Location Disconnect	Overhead Basement	X Underground Electric Panel	Unknown Exterior	X Not Located	Not Present
Observation X Serviceable Deteriorated Low to Ground Ground Line Pre	Damage Splices Low to Driveway sent Clamp not visible	Near end of lifespan Tap Low to Roof X System not visible	Unsafe Low to Pool Loose	Drip Loop Tree Limbs Disconnected	Loose Connections Missing
Comment					
Wiring Notes					
Observation					
Outlets	X Serviceable X Not Operational Missing	X Blocked Not Grounded Loose	No service Reverse Polarity Missing cover	Grounded Near plum Open Neutral Damaged cover	Painted Over Scorching 2 Prong
GFCI Wiring	X Responded X Serviceable Loose	Not Operational X Not fully visible Exposed Wiring	Not Installed Improper Extension Cord	Improper Exposed Missing Conduit	X Unable to Reset Junction Box cover Exterior Box
Lighting	X Not operational Damaged light	Improper Not tested	Switch not operationa Missing cover		Improper wiring Stairway missing switch
Comment Outlet not operation needed.	al at balcony. Unable to res	et GFCI device at balcony	/. Repair is needed. Light i	not operational at main b	athroom - repair is

Notice: Furnishings prevent testing of all outlets and switches (if applicable) - checking is needed prior to closing.

Interior

Doors

Description Condition	X Serviceable	Damaged	Deteriorated	Defects	Worn
Observation	X Oct viocable	Dumaged	Deteriorated	Dordoto	VVOIII
Weather Stripping	X Serviceable	Damaged	Missing	Loose	Repair needed
Entry Door	X Operational	Not Operational	Doorbell not operatio		Damaged
X Doors Serviceable	Damaged	Defective	X Rub	Difficult to Operate	Missing
X Hardware Operation		Missing	Loose	Improper	Damaged
Exterior Doors	X Serviceable	Damage	Gap	Difficult to Operate	Screen door
Glass	Condensation	Tempered	Not Tempered	Unable to Determine	
Latching / Tracks		X Latching Not Operat		Off track	Stiff
Double Lock	Unable to lock	X Missing Lock	Difficult to lock	oao	
Comment					
	room 1 bathroom, loose h	inge / missing pin noted.	Door does not latch at be	edroom 2. Lock handle m	issing at various
		• • • • • • • • • • • • • • • • • • • •	n 2) doors. Adjustment / re		looning at vallous
lecanorie (eigi mam zan		o, boa.oo, boa.oo	, accioi / lajaciiiiciii / i	opan io riocaca.	
Windows					
Description					
Type	Sliding	Single Hung	X Double Hung	Casement	Louver
Турс	Awning	Hopper	Picture	Jalousie	Loaver
Material	Wood	X Metal	Vinyl	Unknown	
Material	VVOod	Nivietai	VIIIyi	OTIKITOWIT	
Observation	_	_	_	_	_
X Operational	Not Operational	Difficult to operate	Damaged	Worn	Security Bars
Glass	Not tempered	Cracked	Scratched	Fogged	Single Pane
Screens	Not Checked	Missing	All Missing	Damaged	Loose
Stains	X Sash Cord	Caulking	Glazing	Hardware Missing	Unable to Lock
Won't latch	Won't close	Won't open	Loose	Damaged	Winder handle
Comment					
Broken sash balance (v	vindow does not stay oper	n) noted at bedroom 1 - r	epair is needed.		
· ·	, ,	,	,		

Notice: Determining condition of all insulated windows is not possible due to temperature, weather and lighting variations. Check with owner for further information. Unable to fully evaluate windows due to blocked access / height / AC.

Interior

Interior Walls					
Description					
Туре	X Drywall	Acoustic Spray	Plaster	Wallpaper	Wood
Tile	Wood Beam	Brick	Log	Brick	Panel
Observation					
Condition	X Serviceable	Needs Repair	Damaged	Uneven	Worn
Moisture	Stains	Damage	Dry	Unable to Determin	е
Cracks	None	Common	Major		
Other	Nails	Holes	Openings	Exposed Framing	Missing
Lead test	Removed wall	Termite	Damage		Not fully visible
Comment					
Notice: The condition of walls	behind wallpaper, paneling and	furnishings cannot be judged. Fu	urnishings prevent full inspection (if	applicable) - checking is needed	prior to closing.
Ceilings					
Description					
Type	Drywall	Acoustic Spray	Plaster	Wallpaper	X Concrete
Open Beam	Wood Beam	Ceiling Tile	Log	Tin	Metal
				Ш	
Observation	Wa			<u> </u>	
Evaluation	X Serviceable	Damaged	Sagging	Low	Worn
Moisture	Stains	Moist	Dry	Unable to Determin	e Damage
Cracks	None	X Common	Major		
Other	Nails	Holes	Openings	Exposed Framing	Uneven
Damaged	Poor insulation	Repaired			
Comment					
Ceiling cracks noted.					
Notice: Determining whether a specialist.	acoustic splayed ceilings contain	asbestos is beyond the scope of	this inspection. For more information	on please contact the American L	ung Association or an asbestos
Floors					
Description			Text to		
Туре	Carpet	Bamboo	X Wood	X Tile	Asbestos-like
Observation					
Condition	X Serviceable	X Worn	Damaged	Termite	Warped
Miscellaneous	X Cracked Tiles	Wood Damage	Loose	Uneven	Squeaks
Worn carpet	Carpet stains	Missing grout	Missing baseboard	Loose carpet	Gap
Comment					
	flooring Lifted flooring	noted by main hathroom	Cracked floor tiles noted a	t main hathroom	
vveai / aging noted at	nooning. Linea nooning i	осоо ву тап вашоот.	Ordoned Hoof thes Hoted d	a main baunoom.	

Notice: Determining odors or stains is not included. The condition of wood flooring below carpet is not inspected. Furnishings & storage prevent full inspection (if applicable) - hidden damage / stains may be present - checking is needed prior to closing.

Features

Features					
Stairway	Serviceable	Uneven	Damaged	Steep	Low Height
Railing	Loose	No Railing	Too Wide	Not graspable	Recommend Upgrade
Ceiling Fan	Operational	Non-Operational	Noise / Wobble	Not Tested	Too Low
Not Tested:	Central Vacuum	Security System	Intercom	Radon Reduction	Invisible fence
	Sound System	Ceiling Fan	Elevator	Murphy Bed	Air Conditioner
	Networking	Shed	Storage Room	X Balcony	Safe
Comment		_			_
	ed at balcony - repair is ne	andad			
	, ,				
Fireplace					
Description			— <u> </u>		
Location	Interior	Living Room	Bedroom	Rear Addition	Basement
Type	Masonry	Prefabricated	Free Standing	Insert	Electric
Observation					
Serviceable	Not Functional	Unsafe	Worn	Near End of Lifespa	
Doors Damaged	No doors	Liner	Joints Deteriorated	Crack	Loose Bricks
Gas Operational	Not Operational	Off	Capped	Improper Piping	
Gas Valve	Functional	Inoperative	In Firebox	Not Tested	Not Visible
Damper Fans / Blowers	Operational Fans Operational	Non-Operational Fans Non-Operation	Missing Blowers Operational	Moisture Blowers Non-Operat	Difficult to operate
Low Clearance	Clean Flue	Caulk Needed	Gas Log	Dirty	II IN/A
	Oledii i ide	Oddin 1400ddd	Ous Log	Librity	
Comment					
Notice: Recommend installing	safety spacer on damper when gas	s logs are present. Wood and ash	nes are not moved for inspection.	Recommend clearing debris and	further evaluation.
Smoke Detector					
Not Responding	Responds	Button Not Respond	i Couldn't Test	Missing	Indicator Light
Additional Suggeste		Covered	Damaged	Loose	X Not Inspected
0					
Comment	avit / enrinklare ware not in	repected. Have the Town	ship check and approve t	the system (nart of State	Certificate of Occupancy
requirements).	exit / spiniklers were not ii	ispected. Have the Town	ізпір спеск апи арргоче і	ine system (part of State	Certificate of Occupancy

Features

Laundry					
Description					
Location	Kitchen	Basement	X Service Area	Kitchen	Bathroom
Observation	_	_	_	_	_
X Plumbing Serviceable Outlet	Damage X Grounded	X Not Fully Visible Not Grounded	Deterioration Non-Operational	Leaks Not Tested	Improper Discharge
220V	220V Operational	220V Non-Operation		Unable to View	
Gas Outlet	Serviceable	Missing Shutoff	Unable to View	Unsafe	Not Tested
	X OK	Not OK	to Interior	Heavy Lint	Damper
Laundry Sink Service	No Sink	Damaged	Worn	Loose	Slow Draining
Faucet Operational	Not operational	Corrosion	Leaks	Hot / Cold	Cross-Connection
Connections Services	Not accessible	Deteriorated	Corrosion	Improper Plumbing	Leaks
Rubber Hoses	Secure Waste	Catch Pan	Alarm	improper ridinibility	Leaks
Rubbel Hoses	Secure waste	Calcii Faii	Alailii		
Comment Regular cleaning of dryer					
Notice: Washing machines and dr machines drains or supply valves.			ralls or flooring under these mac	hines cannot be judged. The inspe	ector does not test washing
Desk / Cabinet / Wet Bar / L	Jtility Sink / Closet				
Observation					
Faucet	Serviceable	Not Operational	Leaks	Cold water only	
Counter	Damage	Deterioration	_		
Plumbing	Leaks	Improper Piping	Icemaker not on	Corrosion	Not vented
Cabinets	Deteriorated	Misaligned			
Comment					
Comment					

Kitchen

Kitchen Sink					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible
Dishes Blocked	Serviceable	Minor Wear	Heavy Wear	Chipped	Loose
Faucet	Hot & Cold Reverse		Non-Operational	Leaking	Corroded
Plumbing	X Serviceable	Corrosion	Improper Pipes	Moisture	X View Restricted
	Slow Drain	Seal Connection	Spray Wand	Counter grout missir	Shutoff
Comment					
Kitchen Cabinet					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible
Countertop	Laminate	X Stone	Wood	Metal	Concrete
Counter	Wear	Damage	Cracked	Chipped	_
Doors	Handle	Off hinge	Difficult to operate	Damaged	Missing
Drawers	Missing Handle	Off track	Not Operational	Damaged	Missing
Cabinets	Moisture stains	Moisture damage	Rodent droppings	Loose hinge	Mold-like stains
Comment					
Cooktop / Oven					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
			_		it it it it it is
Cooktop	X Gas	Electric	Induction		
	No Ignition	Poor Ignition	Burner Inoperable	Element Inoperable	Not Tested
Oven	Not Operational	Not Tested	Cracked Glass	Cracked handle	Loose Door
Gas valve	Installed	X Not Visible	Not Installed	Disabad	Cilta ii
Fan / Hood	X Operational	Inoperable	Missing	Blocked	Filter
Comment					

Notice: Self and/or continuous cleaning operations, clocks, timing devices, lights and thermostat accuracy are not tested during this inspection. Appliances are not moved.

Kitchen

Dishwasher					
Observation					
X Serviceable	Worn	Near end of lifespar	Unsafe	Not Functional	Not fully visible
	No Water			Not tested	Not inspected
Observation	_			_	_
X Door serviceable	Rust / Damage	Won't open	X Seals Serviceable	Seals Deteriorated	Seals Leaking
Drain Line	Air Gap Device	X High-Loop Method	Improperly Installed	Leaking	
Air Gap Device	Not Present	Improper	Leaking		
Not Secured	Removed	Noise	Dedicated shutoff		
Comment					
Comment					
Notice: Determining the adea	uacy of washing and drying functi	ons of dishwashers is not part of the	his inspection		
Notice. Determining the adeq	uacy or washing and drying functi	ons of distiwastiers is not part of the	nis inspection.		
Diamagal					
Disposal					
Observation					
X Serviceable	Worn	Near end of lifespar	Unsafe	Not Functional	X Not fully visible
					Not Inspected
Observation					
Problems	Blades Frozen	Noise	Splash Guard	Wiring Serviceable	Improper Wiring
Missing Clamp	Switch	Wire Splices	Junction Box	Loose wire	
_					
Commont					
Comment					
Appliances					
Observation					
Refrigerator	X Serviceable	Near End of lifespar	n Not Functional	Handle	Not Inspected
Microwave	X Serviceable	Near End of lifespar			Not Inspected
Wiciowave	A Serviceable	INeal Lilu of lilespai	iiiNot Froperly Function	II WOIII	INOT ITISPECTED
Present but not inspec	cted:				
Water Filter	Ice Maker	Wine Refrigerator	Trash Compactor	Blender	Water dispenser
Microwave				_	
_					
Comment					

Special Features - Notice: Refrigerators, freezers and built in ice maker are not part of this inspection.

Bathroom

Location X Main Bathroom X Serviceable	X Bedroom 1 Bathro	om X Master Bathroom Near end of lifespan	Unsafe	Not Functional	Not Inspected Not fully visible
Observation Loose Wax Seal	Tank Loose Cracked	Cracked Did Not Flush	Worn supply Moisture Stain	Water Runs Leaking	
Comment					
Sink Location X Main Bathroom	Y Redroom 1 Rathro	om X Master Bathroom			Not Inspected
Serviceable	X Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
Observation X Plumbing Serviceal X Fixture Serviceable X Drain Serviceable X Cabinet Serviceable Comment Wear noted at bedroof further moisture penet	Leaks Slow Drain Counter Damage m 1 bathroom sink cabin	Supply Valves Corrosion Stopper Defective Cabinet Damage et. Gap noted at master ba	View Restricted Not operational Stopper Missing X Missing caulking/g		Low Pressure Loose Improper drain / vent Mirror Missing end sealing to prevent
Ventilation					
Location X Main Bathroom X Serviceable	X Bedroom 1 Bathro	om X Master Bathroom Near end of lifespan	Unsafe	Not Functional	Not Inspected Not fully visible
Observation Condition Moisture Stain Vents to interior	X Serviceable Duct Broken	Did Not Operate Dirty Vents	Noise Loose Ducts	Should Install No ventilation	Window not operational Long Ducts
Comment					

Bathroom

Shower

Location X Main Bathroom	X Redroom 1 Bathro	om X Master Bathroom		Not Inspected
X Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	X Not fully visible
X Oct viccable	VVOIII	ivear end of mespaironsaic	TVOCT Gricuoriai	X Not raily visible
Observation				
X Walls Serviceable	Damaged	Grout / Caulking Nee Moisture	Crack	Loose
X Plumbing Servicea	ble Slow Drain	Leaking Valve Low Volu	ume Shower Head	Fixture
X Door Serviceable	Unsafe	Unable to Determine Hardwar	e Off Track	X Weather stripping
Mixer	Enclosure Service	abl Corroded Fixtures Doors Di	ifficult Leaking	Damaged Enclosure
Leaking Diverter	Missing fixture cov	ver Damaged fixture Concrete	e Pan Dirty	Leak / Moisture
Difficult to Operate		Grout needed Rec Low		
Comment				
Damaged weather stri	pping noted at main & m	aster bathroom shower doors - repair is	needed.	
N				
Notice: Determining whether s	shower pans are watertight is be	yond the scope of this inspection.		
D. H. L. L				
Bathtub				
Location				
Main Bathroom	X Bedroom 1 Bathro	om X Master Bathroom		Not Inspected
IVIAIII Battillooiii	A Boardon i Batino	Master Batheom		Trot mopeoted
Observation				
Condition	X Serviceable	Damage Worn	End of Lifespan	
Faucet	X Serviceable	Handles Leaking Dripping		Not operational
Whirlpool	Serviceable	High Suction Non-Fun		
Drain	X Serviceable	Non-Operational Stopper		Stopper Damaged
Cracked Tile	Moisture	Grout / Caulk Needer Chips	Defective Diverte	
Leaking	Loose	opo		
Loaking				
Comment				
Steam / Sauna				
Location				
				Not Inspected
Location				Not Inspected
Location Master Bathroom				Not Inspected
Location Master Bathroom Observation	Worn	Near and of lifegran Uncofe	Not Eunstianal	
Location Master Bathroom	Worn	Near end of lifespan Unsafe	Not Functional	Not Inspected Not fully visible
Location Master Bathroom Observation	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	☐ Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	
Location Master Bathroom Observation Serviceable	Worn	Near end of lifespan Unsafe	Not Functional	

Wood Destroying Insect Inspection Report Notice: P	Please read important consumer information	n on page 2 .
Section I. General Information	Company's Business Lic. No.	Date of Inspection
Inspection Company, Address & Phone		6/27/2018
Frank Lin Home Inspections, LLC	Address of Property Inspected	•
·	1125 Maxwell Ln, #X	
-	Hoboken, NJ 7030	
(908) 218-0595		
Inspector's Name, Signature & Certification, Registration, or Lic. #	Structure((s) Inspected
Daniel Lin & Frank Lin	Condomir	•
Section II. Inspection Findings This report is indicative of the condition of the su	6	
guarantee or warranty against latent, concealed or future infestation or defects. Base		
	d on a careful visual inspection of the i	cauny accessible areas of the structure(s)
inspected:		
A. No Visible evidence of a wood destroying insect infestation was observ		
B. Visible evidence of a wood destroying insect infestation was observed	as follows:	
Live Insects (description and location):		
2. Dead Insects, insect parts, frass, shelter tubes, exit holes, or staining (de	scription and location):	
<u> </u>		
3. Visible damage from wood destroying insects were noted as follows (des	scription and location):	
NOTE: This is not a structural damage report. If box B above is checked, it shows	ald be understood that some degree of	damage including hidden damage, may be
present. If any questions arise regarding damage indicated in this report, it is recomm	ended that the buyer or any interested par	rties contact a qualified structural
professional to determine the extent of the damage and the need for repairs.		
Yes No X It appears that the structure(s) or a portion thereof may have been	previously treated. Visible evidence of pos	ssible previous treatment:
The inspecting company can give no assurances with regard to work done by other co	ompanies. The company that performed the	e treatment should be contacted for information
on treatment and any warranty or service agreement which may be in place.		
Section III. Recommendations		
X No Treatment recommended (Explain if Box B in Section II is checked)		
Recommend treatment for the control of:		
Recommend healthent for the control of.		_
Coation IV. Obstructions and Incorposible Areas.		
Section IV. Obstructions and Inaccessible Areas:		The inspector may write out obstructions
The following areas of the structure(s) inspected were obstructed or inaccessible.		or use the following optional key:
Basement		 Fixed ceilings Only visual access Suspended ceilings Cluttered conditions
Crawl Space		3. Fixed wall covering 15. Standing water
X Main Level 1,3,4,5,6,7,8,9,11,13,14,24		4. Floor covering 16. Dense vegetation 5. Insulation 17. Exterior siding
Attic		6. Cabinets or shelving 18. Window well cover
Garage		7. Stored items 19. Wood pile B. Furnishings 20. Snow
X Exterior 11,13,16,17		9. Appliances 21. Unsafe conditions
Porch		10. No access or entry 22. Rigid foam board
Addition		11. Limited access 23. Synthetic stucco 12. No access beneath 24. Duct work, plumbing
Other		and/or wiring
Section V. Additional Comments and Attachments) (these are an integral	part of the report)	
Coolin 177 aditional Commonto and 7 machinions, (mose are arrintegral		_
Attachments		_
Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that	Signature of Buyer. The under	ersigned hereby acknowledges receipt of a
all information regarding W.D.I. infestation, damage, repair, and treatment	copy of both page 1 and page 2 of	of this report and understands the information
history has been disclosed to the buyer.	reported.	
L.	l _v	

Form NPMA-33 Page 1 of 2

Important Consumer Information Regarding the Scope and Limitations Of the Inspection


Please read this entire page, as it is part of the report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces, which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage, which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection doe not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days for the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: FHA and VA require treatment when any active infestation of subterranean termites is found. If signs of subterranean termites but no activity are found in a structure that shows no evidence of having been treated for subterranean termites in the past, than a treatment should be recommended. A treatment may also be recommended for a previously treated structure showing evidence of subterranean termites but no activity if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a license pest control company.
- 3. Obstruction and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attached by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touches structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.

Form NPMA-33 Paç



1) 1125 Maxwell Pl, Hoboken, NJ 07030




2) Entryway




3) Kitchen



4) Laundry




5) Dining room



6) Patio



7) Loose trim



8) Lock missing at balcony screen door



9) Living Room



10) Main bathroom




11) Door lock missing



12) Light not operatoinal



13) Cracked floor tile




14) Loose door weather stripping



15) Den





17) Den






19) Bedroom 1 bathroom




20) Loose door hinge



21) Door lock missing handle



22) Bedroom 2 (master)



23) Door lock handle missing



24) Master bathroom



25) Gap at countertop



26) Door weatherstripping loose