

Inspection Date Report No Client August 19, 2023 85317536

Property Address

XXX 8th St

Jersey City, NJ 07302

Inspector

Daniel Lin (License# 24GI00119200)

Key

This report lists the systems and components inspected by this company. Items not found in this report are considered beyond the scope of this inspection, and should not be considered inspected at this time.

"APPEAR SERVICEABLE" means that we did not observe conditions that would leave us to believe major problems existed with this system or component. The item is cable of being used. Some serviceable items may, however, show wear and tear. Other conditions if applicable, will be noted in the body of the report.

Significantly deficient systems or components will be identified as "Non functional / unsafe / worn / near end of lifespan." When in the inspector's opinion, an item is "significantly deficient", the reason will be within the body of the report.

Please read the entire report for all items.

Present during the Inspection

Listing

Notice: This report contains technical information that may not be readily understandable to the lay person. Therefore a verbal consultation with the inspector is a mandatory part of this inspection report. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of this report's contents. If you were not present during this inspection please call the office to arrange for your verbal consultation.

X Client
X Buyer's Agent
Seller's Agent
Seller
X Occupant
Inspector
Daniel Lin (License# 24GI00119200)
Inspection Date
August 19, 2023
Start Time
1:30 PM
Completion Time
3:30 PM
The weather condition at the time of the inspection was
Partly Cloudy
Approximate temperature during inspection
76° F
Property Information
XXX 8th St, Jersey City, NJ 07302
The subject property inspected
Multi Family Home
Approximate year building was built
Unknown
Stated by

Notice: It is always wise to check with the building department for permit information, especially if additions or alterations are noted.

IMPORTANT NOTICE TO THIRD PARTIES OR OTHER PURCHASERS: RECEIPT OF THIS REPORT BY ANY PURCHASERS OF THIS PROPERTY OTHER THAN THE PARTIES) IDENTIFIED ON THE CONTRACT IS NOT AUTHORIZED BY THE INSPECTOR. THE INSPECTOR STRONGLY ADVISES AGAINST ANY RELIANCE ON THIS REPORT. WE RECOMMEND THAT YOU RETAIN A QUALIFIED PROFESSIONAL INSPECTOR TO PROVIDE YOU WITH YOUR OWN INSPECTION AND REPORT ON THIS PROPERTY.

Summary

This section is provided as a courtesy for quick access to the information within the inspection report.

It is not intended as a substitute for reading the inspection report.

Grounds / Exterior

Cracks & wear noted at sidewalk / walkway - recommend repair & sealing to prevent further wear.

Wear & deterioration noted at deck. Regular service / maintenance is needed to prolong longevity. Heavy wear noted at detached rear deck structure - recommend removal.

Rear exterior stairway handrail not fully graspable - recommend upgrading for safety.

Wear / aging noted at exterior walls. Regular service / maintenance is needed to prolong longevity. Rear siding at end of serviceable lifespan with heavy wear / aging - further evaluation for replacement is needed to prevent moisture penetration / damage.

Chimney flue not fully visible / inspected - recommend cleaning and level 2 inspection by a chimney specialist.

Foundation

Gap noted at basement exterior walkout door - repair is needed. Moisture noted at basement interior. Microbial growth noted at basement interior - remediation is needed. Recommend installation of dehumidifier to reduce moisture levels. Further evaluation for waterproofing is needed. Construction debris noted in basement - removal is needed. Loose & worn bricks & deteriorated mortar noted at interior foundation walls - further evaluation & repair is needed by a masonry contractor to maintain structural integrity of the building.

Twisting noted at main girder and joist - further evaluation for reinforcement is needed by a structural contractor to maintain structural integrity of the building.

Wear / aging noted at basement stairway. Railing missing at basement stairway - installation is needed for safety.

Attic

No access to attic & framing, unable to view / inspect.

Roof

Moisture stains & damage noted at ceilings throughout top floor unit. Evidence of prior patching and repairs noted at roof - request further information from seller. Roof covering showed signs of blistering & open seams. Further evaluation for repair is needed by a roofing contractor. Recommend removal of satellite dish to prevent further wear to roof. Regular maintenance is recommended to the low slope roof. This usually consist of covering all exposed areas with additional aggregate material, repairing any open seams, repairing all / any cracks in the flashing and roofing material.

Plumbing

Abandoned oil tank present at basement - recommend removal. Evidence of previous oil lines observed at basement, inquire with seller regarding previous oil tank placement & proper removal - recommend soil testing for contamination if applicable.

Hot water heaters recently replaced (2018, 2020, 2023), request warranty / permit information from seller.

Heating

Poor location of return and thermostat noted at all heating / cooling systems, relocation is needed to maintain better climate control. Moisture noted at unit 2 catch pan - further evaluation / repair is needed by an HVAC contractor.

Suspected asbestos containing materials noted at heating pipes at basement, abatement by a remediation specialist is needed for health safety.

Electrical

Light not operational at various locations - repair is needed.

Interior & Features

Doors rub frame at unit 3 bedroom 1, unit 4 entry, unit 4 bedroom 1. Chain lock missing at unit 1 entry, unit 4 entry. Door off track at unit 4 HVAC closet. Adjustment / repair is needed. Lock noted at bedroom closet doors - recommend removal for safety.

Various windows show signs of wear / aging. Window screen missing at unit 4 bedroom 1 - installation is needed. Broken sash cord (window does not stay open) noted at unit 2 kitchen, unit 4 kitchen - repair is needed by a window specialist for safety.

Ceiling moisture stains noted throughout top floor unit (see Roof). Active moisture readings noted at unit 2 bathrooms - further evaluation / repair is needed. Microbial growth noted at unit 4 HVAC closet ceiling - further evaluation / remediation is needed.

Uneven flooring noted at interior. Chipped floor tile noted at unit 3 kitchen. Rodent droppings noted at utility closet floor - cleaning & remediation is needed by an exterminating contractor.

Various smoke / CO detectors missing - installation is needed for safety. Smoke detectors / fire exit / sprinklers were not inspected. Have the Township check and approve the system (part of State Certificate of Occupancy requirements).

Regular cleaning of dryer exhaust duct is needed for fire safety. Recommend installation of metal catch pan at washing machine with a moisture sensor / exterior routed drain line to avoid leakage damage to interior finishings. Microbial growth noted at washing machine door seal - cleaning / repair is needed.

Kitchen

Loose faucet noted at kitchen 3 sink - repair / adjustment is needed. Gap noted at kitchen countertop / wall connection, sealing is needed to prevent moisture penetration / damage.

Cooktop knob not operational at unit 3 kitchen - repair is needed. Oven / cooktop tied to GFCI outlet at unit 4 kitchen - correction is needed.

Microwave door trim loose at unit 1 kitchen - repair is needed.

Bathroom

Toilet loose at floor at unit 1 bathroom 1, unit 4 main bathroom, unit 4 primary bathroom - adjustment / repair is needed. Toilet paper holder damaged at unit 1 bathroom 2, unit 4 primary bathroom - repair is needed.

Slow drain noted at unit 3 main bathroom sink - repair is needed. Sink drain stopper missing at unit 1 bathroom 1 - installation is needed. Corrosion noted bathroom sink mirrors. Flexible piping noted at bathroom sink drain lines, prone to clogging / leakage - replacement with rigid piping is needed.

Ventilation fan not operational at unit 3 primary bathroom - repair is needed.

Shower handle damaged at unit 4 main bathroom - repair is needed. Shower mixing valve not operating properly at unit 1 bathroom 2 - repair is needed. Shower door track damaged at unit 3 primary bathroom - repair is needed.

Bathtub not inspected at unit 1 bathroom 1 due to cluttered storage - checking is needed prior to closing. Bathtub drain stoppers missing - installation is needed.

Wood Destroying Insects

Inspection to the wood destroying insect was limited due to cluttered storage, and interior finishings. The inspector can not guarantee that wood destroying insect does not exist. Further investigation may be needed to ensure the house is free of insect damage/infestation.

NOTES

Every effort has been made to perform a detailed and thorough inspection. However, due to interior finishings & furnishings / storage, visibility is limited. Evaluation is conditional to the time of inspection, things may change between the time of inspection and closing. This office recommends a final walkthrough before closing to check areas that were not visible during the time of inspection. Inquire with this office regarding fee & scheduling for the final walkthrough.

Grounds

Driveway					
Description	_	_	_		_
Asphalt	Concrete	Paver	Gravel	Brick	Not Inspected
Observation	10/ 0 000	Name and of life and an	I lu a afa	Nat Francisco	Nat fully coinible
Serviceable Erosion	Worn Deterioration	Near end of lifespan Damaged	Unsafe Ponding	Not Functional Reverse slope	Not fully visible Above siding
Common cracks	Major cracks	Surface raised	Surface settled	Trip hazard	
<u> </u>					
Comment					
Sidewalk / Walkway					
Description					
X Concrete	Asphalt	Brick	Pavers	Unknown	Not Inspected
Observation					
X Serviceable	Worn	Near end of lifespan		Not Functional	Not fully visible (snow)
Erosion	Deterioration	Damaged	Ponding	Reverse slope	Above siding
X Common cracks	Major cracks	Surface settled	Surface raised	Trip hazard	Poor drainage
Cracks & wear noted of	ot oidowalk / walkway ra	sammand ranair 0 acaling	to provent further week		
Cracks & wear noted a	at sidewaik / waikway - re	commend repair & sealing	to prevent further wear	•	
Retaining Wall					
Description					
Wood	Concrete	Masonry Block	Stone	Unknown	Not Inspected
Observation					
Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible
Common cracks	Major cracks	Damaged	Deterioration	Leaning	
Moisture penetration			Moderate moveme		Moisture stains
Comment					

Grounds

Description					
Asphalt	Concrete	Paver	Wood	Stone	Brick
Observation					
Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible
Erosion	Deterioration	Damaged	Ponding	Reverse slope	Above siding
Common cracks	Major cracks	Surface raised	Surface settled	Trip hazard	Loose
Comment					
Deck / Porch / Balcony					
Description	_	_	_		
X Wood	Composite	Concrete	Metal	Unknown	Not Inspected
Observation	_	_	_		
Serviceable	X Worn	Near end of lifespan		Not Functional	Not fully visible
Undersized framing		Bolts missing	Missing hangers	Undersized hangers	
Flashing not visible		Missing flashing	Moisture stains	Framing not visible	Moisture damage
X Railings serviceable Cover	e Railings missing Serviceable	Railings worn Worn	Railings loose Near end of lifespan	Railings too wide Not Inspected	Railings weak Not fully visible
Comment					
Comment Wear & deterioration r	noted at deck. Regular se	ervice / maintenance is ne	eded to prolona lonaevity	. Heavy wear noted at de	tached rear deck
	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r structure - recommend	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r structure - recommend	_	ervice / maintenance is ne	eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration r structure - recommend	_	ervice / maintenance is ne		. Heavy wear noted at de	
Wear & deterioration restructure - recommend	d removal.		eded to prolong longevity	. Heavy wear noted at de	tached rear deck
Wear & deterioration restructure - recommend Gence / Gate Description Wood Observation	d removal.	Chain Link	X Metal	·	Not Inspected
Wear & deterioration of structure - recommend when the structu	Plastic Worn	Chain Link	X Metal Unsafe	Not Functional	Not Inspected Not fully visible
Wear & deterioration of structure - recommend work wood Observation X Serviceable Damaged	Plastic Worn Broken	Chain Link	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected
Wear & deterioration of structure - recommend when the structu	Plastic Worn	Chain Link Near end of lifespan Damaged post	X Metal Unsafe	Not Functional	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend structure - recommend when the structure - reco	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend of the structure of	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend of the structure of	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend of the structure of	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend of the structure of	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend of the structure of	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height
Wear & deterioration of structure - recommend of the structure of	Plastic Worn Broken	Chain Link Near end of lifespan Damaged post	X Metal Unsafe Leaning	Not Functional Corrosion	Not Inspected Not fully visible Low height

Exterior

Exterior Stairway Description Concrete X Wood Metal Stone Unknown Not Inspected Observation X Serviceable Worn Near end of lifespan Unsafe Not Functional Not fully visible No landing Cracks Loose Steps Uneven rise Uneven run Damage Loose railing Improper railing Railings missing Railings too low X Railing not graspable Openings too wide Railings damaged Uneven height Corrosion Rough Finish Comment Rear exterior stairway handrail not fully graspable - recommend upgrading for safety. **Exterior Walls / Trim** Description Vinyl Metal X Wood Composite X Asphalt Shingle Not Inspected Brick Stucco Aluminum Stone Veneer Asbestos-like Concrete Observation Serviceable X Worn X Near end of lifespan Unsafe Not Functional X Not fully visible Damaged Deterioration Defects Cracks Major cracks Movement Siding loose Weep holes covered Earth to soil contact Trim deteriorated Trim missing Trim damaged Flashing missing Siding missing Hole Comment Wear / aging noted at exterior walls. Regular service / maintenance is needed to prolong longevity. Rear siding at end of serviceable lifespan with heavy wear / aging - further evaluation for replacement is needed to prevent moisture penetration / damage. Notice: Wall insulation type and value is not verified. UFFI insulation or hazard are not identified. Conditions inside the wall cannot be judged. Lead paint testing is not performed. Chimney / Exhaust Vent Description X Brick Masonry Block Metal Clay Unknown Not Inspected Observation X Not fully visible X Serviceable X Worn Near end of lifespan Unsafe Not Functional Deterioration Undersized flue Satellite dish X Flue not inspected Damaged Defective Moisture stains Deteriorated mortar Deteriorated brick Loose brick Cracks Leaning Rain cap Rain cap missing Cracked chimney car Corroded chimney co Improper chimney ca Not visible Spark screen Missing spark screen Damaged spark scre Improper spark scree Not visible Corrosion Worn flashing Asbestos Missing flashing Sealing to wall Sealing to roof Missing cricket Comment Chimney flue not fully visible / inspected - recommend cleaning and level 2 inspection by a chimney specialist.

Notice: The interior of the flue was not inspected at this time. We recommend that you retain a qualified chimney sweep to clean and evaluate the flue.

Exterior

Gutters / Downspouts

Description					
X Full	Partial	Missing			Not Inspected
Observation					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
Damaged	Deteriorated	Defective	Disconnected	Leaking	Not draining properly
Debris filled Route down spouts	Loose gutters a Add splash blocks	Missing gutters Add gutter / downspo	Loose down spouts Gutter drains blocked	Damaged down spou Subsurface drains	Missing down spouts Gap
Noute down spouts	a Aud spiasii biocks	Add guiter / downspt	Gutter drains blocked	Subsulface dialits	Gар
Comment					
Notice: Gutters and subsurface	e drains are not water tested for le	eakage or blockage. Regular mair	tenance of drainage systems is req	uired to avoid water problems a	t the roof and foundation.
ose Faucets					
Description					
Exterior	Garage	X Not Located	Interior		Not Inspected
Observation					
Serviceable	Worn	Near end of lifespan		Not Functional	Not fully visible
Corroded	Winterized	Not tested	Inoperative	Broken / missing han	
Shutoff not tested	Recommend winter		Missing anti-siphon v	Exposed pipe	Missing shutoff
Sprinkler system	Leaking sprinkler	Exposed lines	Damaged heads	Loose spray	Sprinkler Not Inspected
Comment					

Notice: Underground pipes cannot be judged for breaks or possible root intrusions. Association maintained systems are not tested. Grove systems are not tested. Hose faucet shutoff valves not tested.

Foundation

Grading					
Description Slope	Level Site	X Minor Slope	Moderate Slope	Steep Slope	Stair stepped
Observation X Serviceable Grading Drainage Landscaping Dying tree	Not Functional X Serviceable X Serviceable Earth to Wood Overhanging limb	Unsafe Reverse Poor Overgrown	Worn Improper Surface Drains (not to Vegetation contact	Near End of Lifespan Erosion Not Visible Tree too close	Not Fully Visible Too high Missing
Notice: This inspection does n	ot include geological conditions o	or site stability information. For ir	formation concerning these condition	ns, a geologist or soils engineer s	hould be consulted.
Description					
Slab-on-grade	Crawlspace	X Basement	Piers	Unknown	
X Entered	Access	No Access	Partial	Not Inspected	Not Fully Visible
Foundation	Poured Concrete	Masonry Block	X Brick	Stone	Unknown
Column	Concrete	X Steel	Wood	Brick	Unknown
Observation		No.		77 h = u	
Serviceable	X Unsafe	X Worn	Near End of Lifespan		Evaluation Needed
Cracks Footings	No Cracks Exposed Footing	Common Cracks Damaged Footing	Cracks Missing Footing	Major Cracks X Not Visible	Deteriorated Parge
Slab	Slab Cracks	Deteriorated	Uneven Flooring	Dirt Floor	X Not visible
Door / Window	Damaged	Worn	Moisture	Soil contact	X
Moisture	X Moisture Stain	X Mold Stains	Damage	Waterproofing preser	X Waterproofing needed
Sump Pump	Operational	Not Functional	Not Tested	Leaking	Improper discharge
Comment					
			re noted at basement interio		
			ce moisture levels. Further orn bricks & deteriorated mo	•	0
			tural integrity of the building		Gadon Wans - IUIUICI
				,	

Notice: All slabs experience some degree of cracking due to shrinkage in the drying process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. The inspector will, at additional cost, re-inspect, provided the client removes floor covering and releases the inspect from damage caused by this process. Floor coverings are not removed during this inspection. The slab was not visible due to carpet and floor coverings - no readily visible problems were found at the time of the inspection.

		Foun	dation		
Framing					
Description					
Framing	X Wood	Steel	Masonry / Brick	Rock	Unknown
Wood Frame	X Joists	Truss	Unknown	Approx Size	Unknown
Observation					
Serviceable	Not Functional	X Unsafe	X Worn	Near End of Lifespar	X Not Fully Visible
Missing Blocks	Missing Straps	Missing reinforcement	Missing hangers	Undersized hangers	Missing fastener
Truss	Broken	Cut	Sagging	Moisture damage	
Joists	Undersized	Twisting	Over notched	Cracked	Deterioration
Beams	Over spanned	X Twisting	Over notched	Cracked	Damaged
Post / Columns	Not fully supported	Loose	Out of plumb	Worn	Corrosion
Anchor Bolts	X Not Visible	Installed	Not Present	X Not Verified	
Shear Panels	X Not Visible	Installed	Not Present	X Not Verified	
Termite damage Comment	Charred framing				
Notice: The inspector does not	determine the effectiveness of a	ny system installed to control or re	emove suspected hazardous subs	tance. No engineering is perform	ed during this inspection.
Basement / Crawlspace					
Description					
Insulation Material	Fiberglass	Cellulose	Vermiculite	Foam	Unknown
Serviceable	Not Functional	Unsafe	Worn	Near End of Lifespar	Not Fully Visible
Observation		_	_		
Loose	Damaged	Incorrectly Installed	None	Rodent holes	Missing
Vapor retarder	Not Functional	Unsafe	Worn	Near End of Lifespar	
Installed	Loose	Damaged	Incorrectly Installed	Not Installed	,
Rodent Droppings	Debris	Cockroach	Asbestos		
Comment					

Ba

ser	nent Stairs					
	Servation Serviceable Uneven step Railings Serviceable Not Graspable	Not Functional Loose steps Loose Damaged Door	Unsafe Stairs Steep Improper	X Worn Low ceiling X Missing	Near End of Lifesp Improper Door Too wide	oan X Not Fully Visible Weak steps Low
W	ear / aging noted at ba	sement stairway. Raili	ng missing at basemer	it stairway - installation i	s needed for safety.	

Attic

Attic

T					
Туре	Full	Partial	Inspection	Entered	Access
Access Location	n Bedroom	Closet	Garage	Hallway	X Not Inspected
Observation		_	_		_
Serviceable	Not Functional	Unsafe	Worn	Near End of Lifespa	
No moisture	Moisture stain	Active moisture	Vent pipe moisture Nail at floor	Chimney moisture Ladder	Mold-like stain Rodent Poison
Exhaust vent	Rodent Droppings	Cluttered storage	INall at floor	Ladder	Rodent Poison
Comment					
No access to attic & fra	aming, unable to view / in	spect.			
	O.	•			
	nce of asbestos or other hazardounting is completed. Not all areas		of this inspection. Tenting a home	for fumigation may cause damag	e to roofs; recommend re-
inspection for damage after ter	nung is completed. Not all aleas	of attic is accessible / visible due	to lack of flooring.		
Framing					
· ·					
Description Roof Frame	X Rafter	Truss	Unknown	Approx Size	X Unknown
Description	X Rafter X Joist	Truss Truss	Unknown Unknown	Approx Size Approx Size	X Unknown X Unknown
Description Roof Frame					
Description Roof Frame Ceiling Frame					
Description Roof Frame Ceiling Frame Observation	X Joist	Trusses Altered	Unknown	Approx Size	X Unknown
Description Roof Frame Ceiling Frame Observation Sagging	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned
Description Roof Frame Ceiling Frame Observation Sagging Missing support	X Joist Broken	Trusses Altered	Unknown Trusses Cut	Approx Size Trusses Damaged	X Unknown Overspanned

Notice: Attic framing not fully visible due to insulation coverings.

Attic

Insulation

Description				
Fiberglass Blown In	Cellulose	Rock Wool	Vermiculite	X Unknown
Approx Depth 4"	6"	8"	10"	Unknown
Observation				
Insulation serviceable No Insulation	Poor Coverage	Compressed	Wrong Side Up	Portions Missing
Vapor Retarder servic Not Present	Not Visible	Improper		
Contacts light Knob & Tube	Rafters Insulated	Loose	Contacts chimney	
Comment				
V49-45				
Ventilation				
Observation				
Ventilation serviceabl Provided	X Not Provided	Blocked Vent	Minimal	Poor
Exhaust Fan Operatic Fan Not Installed	Fan Not Tested	Fan Non-Operation	nal Noise	Inadequate
Screens Damaged Screens Missing	Not Visible			
Comment				

Roof

Description					
Gable	Hip	X Low Slope	Flat Slope	Shed	Mansard
Asphalt	Wood	Tile	Slate	EPDM	X Unknown
Layers	1	2	3+	X Unknown	
X Viewed from Ground	X Viewed with Bir	nocula Viewed from Ladder	X Walked	Viewed with Came	ra
Not visible due to	X Height	Weather	Snow	X Type	Debris
Observation					
Serviceable	X Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
Valley	Missing Shingle	es X Moisture stain	Leak	Moss	Weathering / Aging
Burnt	Cracking	Felt Exposed	Holes	Ridge Components	s Pitch
Improperly Installed	Nails	X Prior Repairs	Unprofessional Rep	oa Underlayment	X Blistering
Alligatoring	Surface Deterio	ration X Open Seams	Ponding / Drainage	Bare	Fishmouth Gaps
Continual Observation	DI				
Comment					
	•	throughout top floor unit. Evid		•	•
	•	ed signs of blistering & open s		'	•
	•	vent further wear to roof. Regu			
	xposed areas with a	dditional aggregate material, r	epairing any open seam	is, repairing all / any crac	cks in the flashing and
roofing material.					
Nation Doofs of this westerial are	after not walked on to o	and actions downers and actable Nat all	tiles/alates are absolved for atte	charant Inquestion is limited. T	he report to an existing of the
		roid causing damage and safety. Not all		•	
		void causing damage and safety. Not all innot, and does not, offer an opinion or v		•	
general quality and condition of		0 0 ,		•	
general quality and condition of exposed Flashings		0 0 ,		•	
general quality and condition of exposed Flashings Description	the roof. The inspector ca	nnot, and does not, offer an opinion or v	warranty as to whether the roof	has leaked in the past, or may be	e subject to future leakage.
general quality and condition of exposed Flashings Description Serviceable	the roof. The inspector ca	nnot, and does not, offer an opinion or v	warranty as to whether the roof l	has leaked in the past, or may be	e subject to future leakage. X Not fully visible
exposed Flashings Description Serviceable Separations Improp	the roof. The inspector ca	nnot, and does not, offer an opinion or v	warranty as to whether the roof	has leaked in the past, or may be	e subject to future leakage.
Exposed Flashings Description Serviceable Separations Improper	the roof. The inspector ca	Near end of lifespan Wall	warranty as to whether the roof	Not Functional Vent Pipes	X Not fully visible Skylight
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps	X Worn Chimney Serviceable	Near end of lifespan Wall Needs repair	Unsafe Drip edge Missing caps	has leaked in the past, or may be	e subject to future leakage. X Not fully visible
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing	X Worn Chimney Serviceable Damaged	Near end of lifespan Wall Needs repair Improper	Unsafe Drip edge Missing caps Missing	Not Functional Vent Pipes Rusty flashing	X Not fully visible Skylight Mastic covered
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged	Near end of lifespan Wall Needs repair Improper	Unsafe Drip edge Missing caps Missing	Not Functional Vent Pipes Rusty flashing	X Not fully visible Skylight Mastic covered
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional
general quality and condition of Exposed Flashings Description Serviceable Separations Improper Observation Vent caps Flashing Skylight Vent Pipe Moisture	X Worn Chimney Serviceable Damaged Serviceable	Near end of lifespan Wall Needs repair Improper Cracked	Unsafe Drip edge Missing caps Missing Damaged	Not Functional Vent Pipes Rusty flashing Moisture	X Not fully visible Skylight Mastic covered Non professional

Notice: Determining the presence of asbestos or hazardous materials is beyond the scope of this inspection. Roofs, skylights and flashing are not water tested for leaks. Notice: Tenting a home for fumigation may cause damage to roofs; recommend re-inspection for damage after tenting is completed.

Plumbing

Main Water Supply Description Shutoff Valve Locatic X Basement Garage Closet Lower bathroom Unknown Material X Copper Galvanized Plastic Unknown Lead 1" X Unknown Approx Size 3/4" 1.5" Not Inspected Observation X Serviceable Worn Near end of lifespan Not Functional X Not fully visible Unsafe Main Valve Operation Not Operational X Not Tested Handle Missing Leaking Pressure Service off X Serviceable Irregular High Pressure Low Copper and Concrete Well pump Softener Softener Installed Softener Leaks Damage Asbestos Extension cord Missing filter Comment Notice: Well pumps are beyond the scope of this inspection. **Water Supply Lines** Description X Pex Material Copper Galvanized X Unknown Lead Observation X Serviceable Near end of lifespan X Not fully visible Worn Unsafe Not Functional **Shutoff Corrosion** Minor Corrosion Active Leaks Damage Moderate Corrosion Major Corrosion Unable to test Pressure Loss Minor Moderate Poor Loss Not Insulated Noise Lack Support Crossed with Sanitar Prior Repair Mixed Asbestos Condensation Comment Notice: Underground pipes or pipes inside walls cannot be judged for sizing, leaks or corrosion. Water quality testing or testing for hazards such as lead is not part of this inspection. Be advised that some "Polybutylene" plastic piping systems have experienced documented problems. **Waste Lines** Description Galvanized X PVC Cast Iron X Unknown Copper Lead Observation X Not fully visible X Serviceable Worn Near end of lifespan Unsafe Not Functional Minor Corrosion Moderate Corrosion Major Corrosion Active Leaks Moisture Stains Damage Lack Support Insufficient Fall Open Line Trap improper Vents X Serviceable None Observed X Not fully visible Improper Missing Asbestos Comment

Notice: City sewer service, septic systems and all underground pipes are not a part of this inspection. Future drainage performance is also not determined. Be advised that some "ABS" plastic piping systems have experienced documented problems. Contact the manufacturer or plumbing expert for further information and evaluation. All of vent/trap pipes were not visible.

Plumbing

Fuel System					
Description					
Shut Off Valve Loc	ea: Exterior	X Basement	Garage	Kitchen	Unknown
Type	X Natural Gas Meter	Oil Tank	LPG Tank	Propane Gas	Fuel Oil
Observation					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
Damaged	Proofed	Not Proofed	Ground/Concrete	Corroded	A Not raily visible
Strained	Lack Support	Improper Pipe	Improper Use	Exposed	X Oil Lines
Low	Unions / Bushings	Copper	Improper des	Поста	A On Lines
Comment					
	scont at bacoment - reco	mmend removal. Evidence	of provious oil lines obse	arved at bacoment incu	iro with collor regarding
		es inside walls or pipes concealed fro rage tanks is not part of this inspectio			ests for gas leaks or pipe size.
	· ·		. ,		
Water Heater					
5					
Description	- ·				
Location	X Basement	Garage	Kitchen	Closet	Unknown
Fuel	X Gas	Electric	Oil		Tankless (see Heating)
Capacity	29 gal	X 40 gal (x4)	80 gal	Tankless	Unknown
Observation					
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
Damaged	Pilot Light	Leaking	Corrosion	Flame	Scorching
Shut Off Valve	X Installed	Missing / Broken	Leaking	Corrosion	Missing Red Label
TPR	X Installed	Not Installed	Missing Pipe	Improper	Too short
Leaking	Missing	Threaded	Capped	Unsafe	Corrosion
Combustion Air	X Supply Air OK	Blocked	Poor		
Vent Flue	X Piping OK	Missing	Loose	Foil tape	Improper
	Back Draft	Improper Angle	Elbows	Clearance	Soot
Seismic Straps	Serviceable	X Not Installed	Improper		
Thermal Blanket	Serviceable	X Not Applicable	Damaged / Missing		
No Catch Pan	Protect	Enclosure Door	Firewall	Garage Floor >18"	No Drain Line
Comment					
	ently replaced (2018, 202	0, 2023), request warranty /	permit information from	seller.	
	, , , , , , , , , , , , , , , , , , , ,	· // / · · · · · · · · · · · · · · · ·			

Notice: Estimate of remaining life is not part of this inspection. Solar systems are not part of this inspection. Hot water recalculating pumps/systems are not part of this inspection. Unable to fully inspect vent pipe.

Heating

	V 01 4	V 01 4	77 01 1	1/ 0/ /	
Location	X Closet	X Closet	X Closet	X Closet	
Heating Type	X Forced Air	X Forced Air	X Forced Air	X Forced Air	
Fuel Type	X Natural Gas	X Natural Gas	X Natural Gas	X Natural Gas	
Approx BTU	X Unknown	X Unknown	X Unknown	X Unknown	
Manufacturer	X Rheem	X Rheem	X Rheem	X Rheem	
Model		X R92PA0701317MSA			4
Serial	X W471600672	X W471600675	X W471600679	X W471600669	
Manufacturing Date	X 2016	X 2016	X 2016	X 2016	
Comment					
Commone					
Notice If a fuel burning booter /	furnace is located in a hadroom	us recommend evolution by a g	unlified heating contractor for cofe	tu and air valume requiremente	Ashestes materials have been
•			ualified heating contractor for safet by laboratory testing and is beyon	•	Asbestos materials have been
commonly used in heating system			•	•	Asbestos materials have been
•			•	•	Asbestos materials have been
commonly used in heating system			•	•	Asbestos materials have been
commonly used in heating syste	ms. Determining the presence of	of asbestos can only be performed	by laboratory testing and is beyone	d the scope of this inspection.	_
commonly used in heating systemating Observation X Serviceable	ms. Determining the presence of	of asbestos can only be performed Near end of lifespan	by laboratory testing and is beyond	d the scope of this inspection. Not Functional	X Not fully visible
ating Observation X Serviceable X Operational	Worn Damaged Not Inspected	Near end of lifespan Not Serviced	by laboratory testing and is beyond Unsafe Unresponsive	Not Functional Not Tested	X Not fully visible
ating Observation X Serviceable X Operational Not Applicable	Worn Damaged Not Inspected	Near end of lifespan Not Serviced Pilot not lit	Unsafe Unresponsive Ignition malfunction	Not Functional Not Tested Utilities off Upgrades	X Not fully visible No Service Corrosion
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation	Worn Damaged Not Inspected Clean / Service	Near end of lifespan Not Serviced Pilot not lit Unusual Noise Unusual flame	Unsafe Unresponsive Ignition malfunction Asbestos	Not Functional Not Tested Utilities off Upgrades	X Not fully visible No Service
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation Burner	Worn Damaged Not Inspected Clean / Service X Burner Serviceable	Near end of lifespan Not Serviced Pilot not lit Unusual Noise	Unsafe Unresponsive Ignition malfunction Asbestos Not visible (closed sy	Not Functional Not Tested Utilities off Upgrades Damaged chamber	X Not fully visible No Service Corrosion Rust / Scorch / Soot
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation Burner Thermostat	Worn Damaged Not Inspected Clean / Service X Burner Serviceable Broken Improperly sized	Near end of lifespan Not Serviced Pilot not lit Unusual Noise Unusual flame X Poor Location	Unsafe Unresponsive Ignition malfunction Asbestos Not visible (closed sy Repairs	Not Functional Not Tested Utilities off Upgrades Damaged chamber Low battery	X Not fully visible No Service Corrosion Rust / Scorch / Soot Loose Insufficient Clearanc
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation Burner Thermostat Air Filter	Worn Damaged Not Inspected Clean / Service X Burner Serviceable Broken Improperly sized Low Temperature	Near end of lifespan Not Serviced Pilot not lit Unusual Noise Unusual flame X Poor Location Dirty	Unsafe Unresponsive Ignition malfunction Asbestos Not visible (closed sy Repairs Hold-down	Not Functional Not Tested Utilities off Upgrades Damaged chamber Low battery Gap	X Not fully visible No Service Corrosion Rust / Scorch / Soot Loose
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation Burner Thermostat Air Filter Furnace	Worn Damaged Not Inspected Clean / Service X Burner Serviceable Broken Improperly sized	Near end of lifespan Not Serviced Pilot not lit Unusual Noise Unusual flame X Poor Location Dirty Air Leaks	Unsafe Unresponsive Ignition malfunction Asbestos Not visible (closed sy Repairs Hold-down Cut Doors	Not Functional Not Tested Utilities off Upgrades Damaged chamber Low battery Gap Moisture Boiler Leaks	X Not fully visible No Service Corrosion Rust / Scorch / Soot Loose Insufficient Clearanc Termination Location Fuel tank leak
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation Burner Thermostat Air Filter Furnace	Worn Damaged Not Inspected Clean / Service X Burner Serviceable Broken Improperly sized Low Temperature High Pressure	Near end of lifespan Not Serviced Pilot not lit Unusual Noise Unusual flame X Poor Location Dirty Air Leaks Low Temperature	Unsafe Unresponsive Ignition malfunction Asbestos Not visible (closed sy Repairs Hold-down Cut Doors Low Pressure	Not Functional Not Tested Utilities off Upgrades Damaged chamber Low battery Gap Moisture	X Not fully visible No Service Corrosion Rust / Scorch / Soot Loose Insufficient Clearanc Termination Location
ating Observation X Serviceable X Operational Not Applicable Complete Evaluation Burner Thermostat Air Filter Furnace Boiler	Worn Damaged Not Inspected Clean / Service X Burner Serviceable Broken Improperly sized Low Temperature High Pressure Leaks	Near end of lifespan Not Serviced Pilot not lit Unusual Noise Unusual flame X Poor Location Dirty Air Leaks Low Temperature Corrosion	Unsafe Unresponsive Ignition malfunction Asbestos Not visible (closed sy Repairs Hold-down Cut Doors Low Pressure TPR	Not Functional Not Tested Utilities off Upgrades Damaged chamber Low battery Gap Moisture Boiler Leaks Fittings	X Not fully visible No Service Corrosion Rust / Scorch / Soot Loose Insufficient Clearanc Termination Location Fuel tank leak

Electronic air cleaners, humidifiers and dehumidifiers are beyond the scope of this inspection - have these systems evaluated by a qualified individual. The inspector is not equipped to thoroughly inspect heat exchangers for evidence of cracks or holes, as this can only be done by dismantling the unit or other technical procedures. Some furnaces are designed in such a way that inspection is almost impossible. Thermostats are not checked for calibration or timed functions. Safety devices are not tested by this company.

Heating

Distributio	n

D	escription					
X	Ducts & Registers	Pipes & Convectors	Pipes & Radiators	Pipes, Radiators &		Electric Baseboard
	Serviceable	Damaged	X Not Fully Visible	Corroded ducts	Corroded pipes	Worn
O	bservation "	Disconnected	Degisters	X Asbestos	Crushed Ducts	Leaks
	Uneven volume	Insulation	Registers Zone Valve	Circulating Pump	Heat Source	Leaks
	Room Radiator	Inoperative	Corrosion	Fittings	Damaged	
	Recommendations	Repairs	Asbestos	Safety Upgrade	Cleaning	
	Humidifier	Moisture	Not connected	Not operational		
C	omment					
		taining materials noted	at heating pipes at base	ment, abatement by a ren	nediation specialist is ne	eeded for health safety.
	'	3	311	,	'	,
No	tice: Adequacy, efficiency or o	van haat distribution of the syste	om through the house is not part	of this inspection. Ashestes mate	orials have been commonly used	d in heating systems. Determining
						midifiers are beyond the scope of
V						
Venti	ng					
_	bservation		77 N. 15 H. 1 H.			
X	Serviceable	Damaged	X Not fully visible	Inaccessible	Unsafe	
	Back Venting	Soot / Rust	Combustible cleara	Improper rise	Improper elbow an	gleWrong Materials
O	bservation	Danamatria Danaman	Induan Fan Dafaat	I In densine d	Maiatuna	
	Terminates near wind Repairs	Barometric Damper Asbestos	Inducer Fan Defect Safety Upgrade	Undersized	Moisture	
]					
Co	omment					
Co	omment					
Co	omment					
Co	omment					
Co	omment					
Co	omment					
Co	omment					
Co	omment					
		been commonly used in heating	systems. Determining the presi	ence of asbestos can ONLY be pe	erformed by laboratory testing ar	nd is beyond the scope of this
No		been commonly used in heating	systems. Determining the prese	ence of asbestos can ONLY be pe	erformed by laboratory testing ar	nd is beyond the scope of this
No	tice: Asbestos materials have pection.	been commonly used in heating	systems. Determining the prese	ence of asbestos can ONLY be pe	erformed by laboratory testing an	nd is beyond the scope of this
No ins	tice: Asbestos materials have pection. Dustion Air	been commonly used in heating	systems. Determining the prese	ence of asbestos can ONLY be po	erformed by laboratory testing ar	nd is beyond the scope of this
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation	_				
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable	Damaged	Not accessible	None Provided	Not visible	nd is beyond the scope of this
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation	_			Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable Blocked	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable Blocked	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable Blocked	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable Blocked	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable Blocked	Damaged	Not accessible	None Provided	Not visible	
No ins Comb	tice: Asbestos materials have pection. Dustion Air bservation Serviceable Blocked	Damaged	Not accessible	None Provided	Not visible	

Air Conditioning

Description									
Not Applicable Type Power X Serviceable X Operational	X	Location Central Air Package Unit 120 Volt Worn Not Tested		Exterior Heat Pump - Air Wall Unit 240 Volt Near end of lifespan Not Inspected	X	Roof Water Source Window Unit Unknown Unsafe Not fully evaluated		Not Located PTAC Geothermal Not Functional No Service	Unknown Split System X Not fully visible Did not respond
Comment									
Observation									
X Serviceable		Worn		Near end of lifespan		Unsafe	Г	Not Functional	X Not fully visible
Inspection Issues		No Power		Below 65		Natural Gas	r	Warm Air Only	Unusual Noise
Electrical Disconnect	X	Present		Not Present		Improper		Exposed Conduit	Not Grounded
Condense Lines	X	Properly Installed	Х	Not Fully Visible		Termination Point		Disconnected	Moisture
		Leaking		No Trap		Too Short		Pinched	
Refrigerant Lines	X	Present		Damaged	X	Not Fully Visible	L	Exposed	Missing
Not Level		Pads	_	Rusted		Float Valve / Pump		Leaking	Too Low
Temperature Differer	1—	System Coil	_	Circulation	-	Junction Box Loose	-	Junction Box Cover	Pump Auxiliary
lce		Recommend Servicing	_	Moisture		Repair needed	L	No catch pan	
Comment									
	_		_				_		

Notice: The inspector does not perform pressure tests on coolant systems: therefore no representation is made regarding coolant damage or line integrity. Subjective judgment of system capacity is not part of the inspection.

Electrical

Electric Panel

Description										
Main Panel Location		Entranceway	X	Basement		Interior		Exterior		Unknown
Sub Panel Location		Basement		Garage	Х	Interior		Attic		Unknown
Rating	Χ	60A	X	100A (x3)		125A		200A		Unknown
Service Wire		Aluminum Service	X	Copper Service		Branch Wire		Unknown	X	Copper Branch
Wiring Methods	X	Metal Conduit		Non-Metallic Cable		Knob & Tube		Plastic Conduit	Х	Unknown
Panel Type	Х	Breaker		Fuse		Voltage	X	120V	Х	220V
Observation										
X Serviceable		Worn		Near end of lifespan		Unsafe		Not Functional		No service
Main Locked		Sub Locked		Power Off		Blocked		Painted, Not Opened		
Main Ground	Х	Present		Loose		Water Line		Ground Rod		Not Visible
No Main		6 Breakers				_		_		
Main Panel	Χ	Serviceable		Improper Wiring		Multi tap		Over Fused		Bushing / Clamps
Labels Missing		Breaker Off		Scorched		Melted		Rust		Not Bonded
Unprotected		Fused Wires		Loose				_		
Sub Panel		Over Fused		Bushings / Clamps		No Labels		Scorched		Melted
Rust		Bus Bar		Not Bonded						
Outdated		Tap Wires		No Antioxidant		Couplers		Dead front cover mis		
Moisture		Mixed Breaker		Loose Breaker		Inoperable Breaker		Upgraded		
Comment										

Notice: Six or fewer breakers usually do not require a main breaker, however this may indicate minimal electrical capacity. If the service amperage is less than 100, upgrade may be needed to operate larger electrical appliances.

Electrical

Description Location Disconnect Observation X Serviceable Deteriorated Low to Ground Ground Line Prese	X Overhead Basement Damage Splices Low to Driveway Clamp not visible	Underground X Electric Panel Near end of lifespan Tap Low to Roof X System not visible	Unknown Exterior Unsafe Low to Pool Loose	Not Located Drip Loop Tree Limbs Disconnected	Not Present Loose Connections Missing
Comment					
Wiring Notes					
Observation Outlets	X Serviceable	X Blocked	No service	Grounded Near plum	Painted Over
Odliels	Not Operational	Not Grounded	Reverse Polarity	Open Neutral	Scorching
	Missing	Loose	Missing cover	Damaged cover	2 Prong
GFCI	X Responded	Not Operational	Not Installed	Improper	Unable to Reset
Wiring	X Serviceable	X Not fully visible	Improper	Exposed	Junction Box cover
Liabtina	Loose	Exposed Wiring	Extension Cord	Missing Conduit	Exterior Box
Lighting	X Not operational Damaged light	Improper Not tested	Switch not operational Missing fixture cover	No control Missing switch cover	Improper wiring Stairway missing switch
Comment	Damaged light	Not toolog	Ivilouing fixture cover	Wilsoning Switch Gover	Ctanway impoing switch
	at various locations - repa	ir is needed			
g.n.net eperational t		15 11554541			

Notice: Furnishings prevent testing of all outlets and switches (if applicable) - checking is needed prior to closing.

Interior

Doors

Description			_	_	_
Condition	X Serviceable	Damaged	Deteriorated	Defects	Worn
	X Serviceable X Operational Damaged Not Operational X Serviceable Condensation X Latching Operational Unable to lock 3 bedroom 1, unit 4 entry, pair is needed. Lock noted	Missing Lock , unit 4 bedroom 1. Chair	Difficult to lock n lock missing at unit 1 en	Difficult to Operate Improper Difficult to Operate Unable to Determine X Off track htry, unit 4 entry. Door off	Stiff
Windows Description					
Type	Sliding	Single Hung	X Double Hung	Casement	Louver
••	Awning	Hopper	Picture	Jalousie	
Material	X Wood	Metal	X Vinyl	Unknown	
	Not Operational Not tempered Not Checked X Sash Cord Won't close signs of wear / aging. Win unit 2 kitchen, unit 4 kitch				Security Bars Single Pane Loose Unable to Lock Winder handle ash cord (window does

Notice: Determining condition of all insulated windows is not possible due to temperature, weather and lighting variations. Check with owner for further information. Unable to fully evaluate windows due to blocked access / height / AC.

Interior

nterior Walls					
Description					
Туре	X Drywall	Acoustic Spray	Plaster	Wallpaper	Wood
Tile	Wood Beam	Brick	Log	Brick	Panel
Observation					
Condition	X Serviceable	Needs Repair	Damaged	Uneven	Worn
Moisture	Stains	Damage	Dry	Unable to Detern	
Cracks	None	Common	Major		
Other	Nails	Holes	Openings	Exposed Framing	g Missing
Lead test	Removed wall	Termite	Damage		Not fully visible
Comment					
Notice: The condition of wa	ills behind wallpaper, paneling and	furnishings cannot be judged. Fu	urnishings prevent full inspectio	n (if applicable) - checking is nee	ded prior to closing.
-					
Description	V Dm sucell	A counting Comment	Disates	NA/allmamam	Comente
Туре	X Drywall	Acoustic Spray	Plaster	Wallpaper	Concrete
Open Beam	Wood Beam	Ceiling Tile	Log	Tin	Metal
Observation	_				
Evaluation	X Serviceable	Damaged	Sagging	Low	Worn
Moisture	X Stains	X Moist	Dry	Unable to Detern	nine Damage
Cracks	None	Common	Major		
Other	Nails	Holes	Openings	Exposed Framing	gUneven
Damaged	Poor insulation	Repaired			
	ins noted throughout top flowth noted at unit 4 HVAC				urther evaluation / repair is
Notice: Determining whethe specialist.	er acoustic splayed ceilings contair	n asbestos is beyond the scope of	this inspection. For more inform	mation please contact the America	an Lung Association or an asbestos
Description	0	1	V W	V T" -	A -1: 4: 111
Туре	Carpet	Laminate	X Wood	X Tile	Asbestos-like
Observation					
Condition	X Serviceable	Worn	Damaged	Termite	Warped
Miscellaneous	Cracked Tiles	Wood Damage	Loose	X Uneven	Squeaks
Worn carpet	Carpet stains	Missing grout	Missing baseboa	rd Loose carpet	Gap
Comment					
Uneven flooring note needed by an extern		r tile noted at unit 3 kitche	en. Rodent droppings no	oted at utility closet floor -	cleaning & remediation is

Notice: Determining odors or stains is not included. The condition of wood flooring below carpet is not inspected. Furnishings & storage prevent full inspection (if applicable) - hidden damage / stains may be present - checking is needed prior to closing.

Features

Features					
Stairway	X Serviceable	Uneven	Damaged	Steep	Low Height
Railing	Loose	No Railing	Too Wide	Not graspable	Recommend Upgrade
Ceiling Fan	Operational	Non-Operational	Noise / Wobble	Not Tested	Too Low
Not Tested:	Central Vacuum	Security System	Intercom	Radon Reduction	Invisible fence
	Sound System	Ceiling Fan	Elevator	Murphy Bed	Air Conditioner
	Networking	Shed	Storage Area	Balcony	Safe
Comment					
Circulage					
Fireplace					
Description					
Location	Interior	Living Room	Bedroom	Rear Addition	Basement
Туре	Masonry	Prefabricated	Free Standing	Insert	Electric
Observation					
Serviceable	Not Functional	Unsafe	Worn	Near End of Lifespar	Damaged
Doors Damaged	No doors	Liner	Joints Deteriorated	Crack	Loose Bricks
Gas Operational	Not Operational	Off	Capped	Improper Piping	Loode Brioks
Gas Valve	Functional	Inoperative	In Firebox	Not Tested	Not Visible
Damper	Operational	Non-Operational	Missing	Moisture	Difficult to operate
Fans / Blowers	Fans Operational	Fans Non-Operation	ona Blowers Operational	Blowers Non-Operati	N/A
Low Clearance	Clean Flue	Caulk Needed	Gas Log	Dirty	
Comment					
Notice: Recommend installing	g safety spacer on damper when g	as logs are present. Wood and a	shes are not moved for inspection.	Recommend clearing debris and t	further evaluation.
Smoke Detector					
Not Responding	Responds	Button Not Respon	di Couldn't Test	X Missing	Indicator Light
Additional Suggest		Covered	Damaged	Loose	X Not Inspected
Comment					
	letectors missing - installa	tion is needed for safety	. Smoke detectors / fire exi	t / sprinklers were not ins	pected. Have the
	approve the system (part o			,	'
· ·	, , ,		,		

Features

Laundry Description Location Kitchen Basement X Service Area Kitchen Bathroom Observation X Plumbing Serviceable X Not Fully Visible Improper Discharge Damage Deterioration Leaks X Grounded Not Grounded Non-Operational Not Tested Outlet 240V 240V Operational 240V Non-Operationa 240V not tested Unable to View Gas Outlet Serviceable Missing Shutoff Unable to View Unsafe Not Tested **Dryer Venting** X OK Not OK to Interior Heavy Lint Damper Laundry Sink Service Worn Slow Draining No Sink Damaged Loose **Faucet Operational** Corrosion Leaks Hot / Cold Cross-Connection Not operational Connections Service: Not accessible Deteriorated Corrosion Improper Plumbing Leaks Rubber Hoses Secure Waste X Catch Pan Alarm Comment Regular cleaning of dryer exhaust duct is needed for fire safety. Recommend installation of metal catch pan at washing machine with a moisture sensor / exterior routed drain line to avoid leakage damage to interior finishings. Microbial growth noted at washing machine door seal - cleaning / repair is needed. Notice: Washing machines and dryers are not tested / moved during this inspection; condition of walls or flooring under these machines cannot be judged. The inspector does not test washing machines drains or supply valves. Water supply valves if turned may be subject to leaking. Desk / Cabinet / Wet Bar / Utility Sink / Closet Observation Faucet Serviceable Not Operational Leaks Cold water only Counter Damage Deterioration Plumbing Improper Piping Not vented Leaks Icemaker not on Corrosion Cabinets Deteriorated Misaligned Comment

Kitchen

Kitchen Sink						
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible	
Dishes Blocked	Serviceable	Minor Wear	Heavy Wear	Chipped	X Loose	
Faucet	Hot & Cold Reverse		Non-Operational	Leaking	Corroded	
Plumbing Loose Drain Line	X Serviceable Slow Drain	Corrosion Leaking Drain Line	Improper Pipes Spray Wand	Moisture X Counter grout missing	X View Restricted Shutoff	
	Slow Dialii	Leaking Diain Line	Opiay Wallu	A Counter grout missing	Ollatoli	
	Comment Loose faucet noted at kitchen 3 sink - repair / adjustment is needed. Gap noted at kitchen countertop / wall connection, sealing is needed to prevent					
moisture penetration /		-,		-	д р	
Kitchen Cabinet						
X Serviceable	Morn	Near and of lifeanan	Lincofo	Not Functional	Not fully visible	
	Worn	Near end of lifespan			Not fully visible	
Countertop Counter	Laminate Wear	X Stone Damage	Wood Cracked	Metal Chipped	Concrete	
Doors	Handle	Hinge	Difficult to operate	Damaged	Missing	
Drawers	Missing Handle	Off track	Not Operational	Damaged	Missing	
Cabinets	Moisture stains	Moisture damage	Rodent droppings	Loose hinge	Mold-like stains	
Comment						
Cooktop / Oven						
X Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible	
Cooktop	X Gas	Electric	Induction			
Coomop	No Ignition	Poor Ignition	Burner Inoperable	Element Inoperable	Not Tested	
Oven	Not Operational	Not Tested	Cracked Glass	Cracked handle	Loose Door	
Gas valve	Installed	X Not Visible	Not Installed			
Fan / Hood	X Operational	Inoperable	Missing	Blocked Anti-tip	Filter	
0				Anti-up		
Control knob not one	rational at unit 2 kitchon	repair is needed. Oven / o	cookton tind to GECL out	lot at unit 4 kitchon corro	ction is pooded	
Cooktop knob not ope	Tational at unit 5 kitchen -	repair is needed. Overi / C	booklop lied to Gi Gi out	iet at unit 4 kitchen - cone	ction is needed.	

Notice: Self and/or continuous cleaning operations, clocks, timing devices, lights and thermostat accuracy are not tested during this inspection. Appliances are not moved.

Kitchen

hwasher					
Observation X Serviceable	Worn No Water	Near end of lifespan	Unsafe	Not Functional Not tested	Not fully visible Not inspected
Observation X Door serviceable Drain Line Air Gap Device Not Secured Comment	Rust / Damage Air Gap Device Not Present Removed	Won't open X High-Loop Method Improper Noise	X Seals Serviceable Improperly Installed Leaking Dedicated shutoff	Seals Deteriorated Leaking	Seals Leaking
	acy of washing and drying function	ons of dishwashers is not part of th	is inspection.		
Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	Not fully visible Not Inspected
Observation Problems Missing Clamp	Blades Frozen Switch	Noise Wire Splices	Splash Guard Junction Box	Wiring Serviceable Loose wire	Improper Wiring
Comment					
Observation					
Refrigerator Microwave					Not Inspected Not Inspected
Present but not inspect Water Filter Microwave		Wine Refrigerator	Trash Compactor	Blender	Water dispenser
Comment					
	ose at unit 1 kitchen - rep	pair is needed.			
	Observation X Serviceable Observation X Door serviceable Drain Line Air Gap Device Not Secured Comment Notice: Determining the adequation Serviceable Observation Problems Missing Clamp Comment pliances Observation Refrigerator Microwave Present but not inspect Water Filter Microwave Comment	Observation X Serviceable Worn No Water Observation X Door serviceable Rust / Damage Drain Line Air Gap Device Not Present Removed Comment Notice: Determining the adequacy of washing and drying functions Sposal Observation Serviceable Worn Observation Problems Blades Frozen Missing Clamp Switch Comment pliances Observation Refrigerator X Serviceable Serviceable Microwave X Serviceable Present but not inspected: Water Filter Ice Maker Microwave Comment	Observation X Serviceable	Observation X Serviceable	Observation X Serviceable

Special Features - Notice: Refrigerators, freezers and built in ice maker are not part of this inspection.

		Bath	nroom		
oilet					
Location					
X Unit 1 Bathroom X Serviceable	X Unit 2 Bathroom Worn	X Unit 3 Bathroom Near end of lifespan	X Unit 4 Bathroom Unsafe	Not Functional	Not Inspected Not fully visible
Observation					
X Loose Wax Seal	Tank Loose Cracked	Cracked Did Not Flush	Worn supply Moisture Stain	Water Runs Leaking	
Comment					
		main bathroom, unit 4 prin athroom - repair is needed		ionit, repair le necedeu.	Silot paper floraci
ink Location X Unit 1 Bathroom	X Unit 2 Bathroom	X Unit 3 Bathroom	X Unit 4 Bathroom		Not Inspected
Serviceable	Worn	Near end of lifespan	Unsafe	Not Functional	X Not fully visible
Observation X Plumbing Servicea X Fixture Serviceable X Drain Serviceable X Cabinet Serviceable	Leaks X Slow Drain	Supply Valves Corrosion Stopper Defective Cabinet Damage	View Restricted Not operational X Stopper Missing Missing caulking/gr	Leaking Loose Spray Loose Drain Line ou X Mirror damaged	Low Pressure Loose Improper drain / vent Mirror Missing
Comment					
		repair is needed. Sink dra ted at bathroom sink drain			tion is needed. Corrosion with rigid piping is needed.
entilation					
Location X Unit 1 Bathroom X Serviceable	X Unit 2 Bathroom Worn	X Unit 3 Bathroom Near end of lifespan	X Unit 4 Bathroom Unsafe	Not Functional	Not Inspected Not fully visible
Observation Condition Moisture Stain Vents to interior	X Serviceable Duct Broken	Did Not Operate Dirty Vents	Noise Loose Ducts	Should Install No ventilation	Window not operation
Comment					
Ventilation fan not ope	erational at unit 3 primary	bathroom - repair is neede	ed.		

Bathroom

Shower

	Location X Unit 1 Bathroom X Serviceable	X Unit 2 Bathroom Worn	X Unit 3 Bathroom Near end of lifespar	X Unit 4 Bathroom Unsafe	Not Functional	Not Inspected X Not fully visible
	Observation X Walls Serviceable X Plumbing Serviceable X Door Serviceable X Mixer Leaking Diverter Difficult to Operate Comment	Damaged Slow Drain Unsafe Enclosure Servicea Missing fixture cove Low pressure		Low Volume	Crack Shower Head Off Track Leaking Dirty Damaged floor	Loose X Fixture Weather Stripping Damaged Enclosure Leak / Moisture
	Shower handle damage needed. Shower door to	rack damaged at unit 3 p	rimary bathroom - repair		erating properly at unit 1 b	oathroom 2 - repair is
Rs	Notice: Determining whether st	nower pans are watertight is beyo	and the scope of this inspection.			
טנ	Location					
	X Unit 1 Bathroom	X Unit 2 Bathroom	X Unit 3 Bathroom	X Unit 4 Bathroom		Not Inspected
	Observation Condition Faucet Whirlpool Drain Cracked Tile Leaking Comment	X Serviceable X Serviceable Serviceable X Serviceable Moisture Loose	Damage Handles Leaking High Suction Non-Operational Grout / Caulk Neede	Worn Dripping Non-Functional X Stopper Missing Chips	End of Lifespan Corrosion Not Tested Slow Drain Defective Diverter	Not operational Stopper Damaged Damaged Surface
	Bathtub not inspected a installation is needed.	at unit 1 bathroom 1 due	to cluttered storage - che	cking is needed prior to	closing. Bathtub drain sto	ppers missing -
St	Steam / Sauna Location Primary Bathroom Not Inspected					
	Observation Serviceable	Worn	Near end of lifespar	n Unsafe	Not Functional	Not fully visible
	Comment					

Wood Destroying	Insect Inspection Report Notice:	Please read important consumer information	on page 2 .		
Section I. General I	nformation	Company's Business Lic. No.	Date of Inspection		
Inspection Company, A			8/19/2023		
Frank Lin Home Inspections, LLC		Address of Property Inspected			
844 Star View Way		XXX 8th St			
Bridgewater, NJ 08807		Jersey City, NJ 7302			
(908) 218-0595					
	ature & Certification, Registration, or Lic. #	Structure(s)			
Daniel Lin & Frank Lin	Y	Multi Family			
	on Findings This report is indicative of the condition of the				
	against latent, concealed or future infestation or defects. Ba	sed on a careful visual inspection of the re	eadily accessible areas of the structure(s)		
inspected:					
	dence of a wood destroying insect infestation was obse				
	nce of a wood destroying insect infestation was observe	d as follows:			
1. Live Insec	ts (description and location):				
2. Dead Inse	cts, insect parts, frass, shelter tubes, exit holes, or staining (o	description and location):			
2 Vieible de	and the first state of the first state of the state of th	Innation and Innation).			
3. Visible da	mage from wood destroying insects were noted as follows (o	lescription and location):			
	tructural damage report. If box B above is checked, it should be a saise regarding damage indicated in this report, it is recomparate to the said of t				
	ne the extent of the damage and the need for repairs.	interided that the buyer of any interested par	lies contact a qualified structural		
	ppears that the structure(s) or a portion thereof may have bee	on proviously treated. Visible avidence of pos	sible provious treatment:		
Tes NO A IL a	opears that the structure(s) of a portion thereof may have been	en previously treated. Visible evidence of pos	sible previous treatment.		
The increating compar	y can give no assurances with regard to work done by other	companies. The company that performed the	transment should be contested for information		
	varranty or service agreement which may be in place.	companies. The company that performed the	treatment should be contacted for information		
Section III. Recomn					
_	commended (Explain if Box B in Section II is checked) tment for the control of:				
Recommend frea	unient for the control of.				
Section IV Obstruc	tions and Inaccessible Areas:				
			inspector may write out obstructions		
	the structure(s) inspected were obstructed or inaccessible.		ise the following optional key:		
	7,9,11,12,13,14,24		Fixed ceilings 13. Only visual access Suspended ceilings 14. Cluttered conditions		
Crawl Space	1245679044424494		Fixed wall covering 15. Standing water		
X Main Level	1,3,4,5,6,7,8,9,11,13,14,24		Floor covering 16. Dense vegetation		
X Attic	10		Insulation 17. Exterior siding Cabinets or shelving 18. Window well cover		
Garage X Exterior	11,13,16,17		Stored items 19. Wood pile		
Porch	11,13,10,17	l l	Furnishings 20. Snow		
			Appliances 21. Unsafe conditions		
Addition			No access or entry 22. Rigid foam board 23. Synthetic stucco		
Other 11. Limited access 23. Synthetic stucco 12. No access beneath 24. Duct work, plumbing					
Section V. Additional Comments and Attachments) (these are an integral part of the report)					
Section V. Addition	at comments and Attachments) (these are an integr	ai part of the report)			
ı 					
Attachments					
Attachments					
Cinnature of Callend	a) an Ownerda) if an financian Callinson I and a state of	Signature of Donor The	in ad haraba administrative		
	s) or Owner(s) if refinancing. Seller acknowledges that	1 -	signed hereby acknowledges receipt of a		
	g W.D.I. infestation, damage, repair, and treatment	copy of both page 1 and page 2 of this report and understands the information			
history has been disclo	sed to the buyer.	reported.	!		
, , , , , , , , , , , , , , , , , , ,			!		
X		ĮΧ			

X Form NPMA-33 Page 1 of 2

Important Consumer Information Regarding the Scope and Limitations Of the Inspection


Please read this entire page, as it is part of the report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces, which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage, which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection doe not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days for the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: FHA and VA require treatment when any active infestation of subterranean termites is found. If signs of subterranean termites but no activity are found in a structure that shows no evidence of having been treated for subterranean termites in the past, than a treatment should be recommended. A treatment may also be recommended for a previously treated structure showing evidence of subterranean termites but no activity if there is no documentation of a liquid treatment by a licensed pest control company within the previous five years unless the structure is presently under warranty or covered by a service agreement with a license pest control company.
- 3. Obstruction and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attached by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touches structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.

Form NPMA-33 Paç



XXX 8th St, Jersey City, NJ 07302




Rear yard



Wear at rear deck



Rear exterior




AC condenser



AC condenser



Heavy wear at rear facade



Basement stairway



Basement



Basement



Heavy wear & deterioration at foundation wall



Heavy wear & deterioration at foundation wall



Oil tank




Water meter & main shutoff vale



Gas meters & main shutoff valve



Construction debris



Basement



Twisting at main girder



Electric meter & main breakers




Electric panel




Suspected asbestos containing materials at heating pipes



Electric panel




Twisting at main girder




Hot water heaters



Entryway




Unit 1 Kitchen



Laundry




Electric panel



Electric panel



Unit 1 Bathroom



Unit 1 dining room




Unit 1 heating / cooling system




Unit 1 bedroom 1



Unit 1 living room



Unit 1 bathroom 2




Unit 1 bedroom 2



Unit 2 kitchen




Laundry




Unit 2 living room



Electric panel



Electric panel




Unit 2 main bathroom




Ceilng moisture damage




Unit 2 bedroom 1



Unit 2 bedroom 2



Unit 2 den



Unit 2 heating / cooling system



Moisture at catch pan



Unit 2 bedroom 3




Damaged siding




Unit 2 primary bathroom




Ceiling moisture damage



Unit 3 kitchen




Laundry



Unit 3 main bathroom




Peeling paint



Unit 3 living room



Electric panel




Electric panel



Unit 3 bedroom 1



Unit 3 bedroom 2




Unit 3 den




Unit 3 heating / cooling system



Rodent droppings



Unit 3 bedroom 3




Unit 3 primary bathroom



Shower door damaged



Unit 4 kitchen



Ceiling moisture stain




Laundry



Unit 4 living room



Electric panel




Electric panel



Unit 4 main bathroom



Unit 4 bedroom 1



Unit 4 bedroom 2



Unit 4 den




Unit 4 heating / cooling system



Ceiling moisture damage




Microbial growth at ceiling



Unit 4 bedroom 3



Ceiling moisture stain




Unit 4 primary bathroom



Roof access




Roof



Roof



AC condensers



Repair at roof



Roof drain



Blistering at roof